INSTRUCTIONS PARTITION TOP BOX HANDHOLE CUTOUT PARTITION FLAP G **PARTITION** BROWN CRAFT SIDE UP HANDHOLE CUTOU **PARTITION** END FLAR PARTITION FLAP ASSEMBLED END ELAP 4 VFOLDER19 VFILE 19 FINISHED TOP 6 --PURCHASE SEPARATELY--FOR USE WITH THE **VFile19** AND THE **VFile25**

20101203VFILE19INSTRUCTIONS



VFILE 19

NOTE:

PRE-FOLD ALL SCORED FLAPS FOR CLEAN EDGE PRIOR TO FOLDING FOR FINAL ASSEMBLY.

VFILE 19 TOP (A through D)

- fold <u>corner flaps</u> of the <u>short sides</u> up. Fold short sides up.
- WITH THE CORNER FLAPS OF THE LONG SIDES
 POINTING OUT, FOLD THE LONG SIDES OVER THE
 CORNER FLAPS OF THE SHORT SIDES. THIS WILL
 ALLOW THE CORNER FLAPS OF THE LONG SIDE TO
 LAY AGAINST THE SHORT SIDE.
- (3) FOLD IN SHORT SIDES & LOCK IN SLOTS.

VFILE 19 BOX (E through G)

- FOLD SINGLE FLAP IN AND AGAINST SIDE OF BOX INTERIOR.
- (5) FOLD END FLAPS FLAT AGAINST CENTER FLAP.
- 6 FOLD CENTER AND END FLAPS FLUSH WITH BOTTOM OF BOX & SET UPRIGHT.
- 7 USING FINGER HOLES, PULL END FLAPS IN & AGAINST SIDES OF BOX INTERIOR.
- (8) FOLD SINGLE FLAP TO BOTTOM OF BOX.
- 9 FLAPS REMAINS UPRIGHT PRIOR TO INSERTING PARTITIONS.

VFOLDER 19 PARTITION (J)

- WITH PARTITIONS FOLDED IN HALF ALONG THE SCORE (WHITE SIDE OUT), FOLD PARTITION FLAPS OUT.
- INSERT EACH PARTITION IN BOX ALIGNING CUTOUTS WITH HANDHOLES.

VFILE19 BOX (H)

- 12) FOLD IN LONG SIDE FLAP.
- FOLD IN SHORT SIDE FLAP LOCKING PARTITIONS IN SLOTS.